

TABLE OF CONTENTS

Executive Summary	i
Identifying Transportation Needs on Rainier Avenue South	i
Rainier Avenue South Today.....	i
Rainier Avenue South Tomorrow.....	i
Performance Objectives	ii
Key Considerations.....	ii
Major Recommendations.....	iii
Phase One Improvements	iii
Rainier Avenue South Improvements.....	iii
Hardie Avenue Southwest Improvements	iii
Chapter 1: Introduction	1
City Transportation Goals and Study Objectives	1
Study Area	2
Planning Process.....	4
Participants	4
Project Planning Assumptions.....	4
Public Involvement.....	5
Chapter 2. Existing Transportation Conditions	6
Functional Street Classification	6
Transit Services, Facilities, and Usage.....	8
Traffic Volumes	12
Hourly Distribution of Daily Traffic Volumes.....	15
Vehicle Travel Speed Survey.....	17
Bus Travel Speed Surveys	19
Comparison of Vehicle and Bus Travel Speeds.....	22
Traffic Accidents.....	31
Rainier Avenue.....	31
High Accident Locations Within the Larger Study Area.....	32
Plans and Programs	40
I-405 Corridor	40
King County West Hill Community Transportation Plan.....	41
Renton Arterial Plan	41
Pedestrian/Bike Plan.....	43
Comprehensive Citywide Walkway Study (May 2003).....	43
Chapter 3. Baseline Transportation Conditions	44
Land Use Assumptions	44
Transportation Network Assumptions	45
Traffic Conditions	50
Traffic Volumes	50
Traffic Operations Analysis	53
Chapter 4. Identification and Evaluation of Improvement Options	55
Steps to Develop Recommendation	55
Fatal Flaw Analysis and First Screening.....	56
Areas of Emphasis.....	56
Performance Objectives.....	56
Major Themes	57
Roadway Improvement OPTIONS.....	57
Transit Improvements- Rainier Route Option.....	59
Transit Improvements - Hardie Route Option	59
Pedestrian/Urban Design Improvement Options.....	59
Second Screening	61
Roadway and Pedestrian/Urban Design Improvements	61
Transit Alternatives (Hardie Avenue BAT Lanes VS Rainier Avenue BAT Lanes).....	61
Chapter 5. Recommendations and Implementation Plan	65
Study Recommendations.....	65

First Phase Project Recommendations	69
Rainier Avenue South Improvements.....	69
Hardie Avenue Southwest Improvements	69

LIST OF FIGURES

Figure 0. Recommended Phase 1 Improvements	iv
Figure 1-1. Rainier Avenue Corridor Study Area	3
Figure 1-2. Study Process	4
Figure 2-1. Functional Street Classification in the Study Area	7
Figure 2-2. Locations of Bus Stops With Daily Boardings and Alightings.....	11
Figure 2-3. Renton 2004 Traffic Flow Map – Study Area Vicinity	13
Figure 2-4. Average Daily Traffic Trends (1988 – 2002).....	14
Figure 2-5. Hourly Traffic Volumes on Rainier Avenue South, South of South Grady Way (Average Weekday in 2002).....	15
Figure 2-6. Hourly Traffic Volumes on Rainier Avenue South, North of South 7 th Street (Weekday in 2002)	16
Figure 2-7. Hourly Traffic Volumes on Rainier Avenue South, South of South 2 nd Street (Weekday in 2002)	16
Figure 2-8. Two-Day Average of Vehicle Travel Speeds From 11 AM to 6 PM (June 17 th and 18 th , 2003)....	18
Figure 2-9. Two-Day Average of Vehicle Travel Speeds From Noon to 1 PM (June 17 th and 18 th , 2003) ...	18
Figure 2-10. Two-Day Average of Vehicle Travel Speeds From 4 PM to 5 PM (June 17 th and 18 th , 2003) .	19
Figure 2-11. Transit Travel Speeds Between South 7 th Street and South Grady Way*	20
Figure 2-12. Transit Travel Speeds Between South 4 th Place and South 7 th Street*	20
Figure 2-13. Transit Travel Speeds Between South 3 rd Place and South 4 th Place*	21
Figure 2-14. Transit Travel Speeds Between South 3 rd Street and South 3 rd Place*	21
Figure 2-15. Transit Travel Speeds Between South 2 nd Street and South 3 rd Street*	22
Figure 2-16. Comparisons of Vehicle Speeds with Sound Transit Bus Speeds on Southbound Rainier Avenue South During Mid-Day Hour (1-2 PM)	23
Figure 2-17. Comparisons of Vehicle Speeds with Sound Transit Bus Speeds on Northbound Rainier Avenue South During Mid-Day Hour (1-2 PM).....	23
Figure 2-18. Comparisons of Vehicle Speeds with King County Metro Bus Speeds on Southbound Rainier Avenue South During Mid-Day Hour (Noon-1 PM).....	24
Figure 2-19. Comparisons of Vehicle Speeds with King County Metro Bus Speeds on Northbound Rainier Avenue South During Mid-Day Hour (Noon-1 PM)	24
Figure 2-20. Comparisons of Vehicle Speeds with Sound Transit Bus Speeds on Southbound Rainier Avenue South During PM Peak Hour (4-5 PM).....	25
Figure 2-21. Comparisons of Vehicle Speeds with Sound Transit Bus Speeds on Northbound Rainier Avenue South During PM Peak Hour (4-5 PM).....	25
Figure 2-22. Comparisons of Vehicle Speeds with King County Metro Bus Speeds on Southbound Rainier Avenue South During PM Peak Hour (3-4 PM).....	26
Figure 2-23. Comparisons of Vehicle Speeds with King County Metro Bus Speeds on Northbound Rainier Avenue South During PM Peak Hour (3-4 PM).....	26
Figure 2-24. AM and PM Peak Hour Average Intersection Delays and Levels of Service	29
Figure 2-25. 2002 Intersection Approach Levels of Service for PM Peak Hour	30
Figure 2-26. I-405 Implementation Program Under Option C.....	42
Figure 3-1. 2015 Transportation Network Assumptions.....	47
Figure 3-2. 2030 Transportation Network Assumptions.....	48
Figure 3-2A. Revised I-405/SR 167 Interchange Master Plan Concept.....	49
Figure 3-3. 2002, 2015 and 2030 PM Peak Hour Traffic Volumes	52
Figure 3-4. 2002, 2015 and 2030 PM Peak Hour Levels of Service	54
Figure 4-1. Process to Develop Recommendation.....	55
Figure 4-2. Rainier Avenue Corridor Improvement Options	58
Figure 5-1. Study Recommendations	67
Figure 5-2. Aerial Overview of Study Recommendations	68
Figure 5-3. Rainier Avenue Current View	70
Figure 5-4. Rainier Avenue Conceptual Future View	70
Figure 5-5. Hardie Avenue Current View.....	71
Figure 5-6. Hardie Avenue Conceptual Future View	71
Figure 5-7. Aerial Overview of Phase One Recommendations	72

LIST OF TABLES

Table 2-1. Existing Weekday Bus Volumes on Rainier Avenue (Spring 2003)	9
Table 2-2. Summary of Bus Passenger Activity at the Stops on Rainier Avenue (Spring 2003)	10
Table 2-3. Level of Service Definition	27
Table 2-4. Midblock Traffic Accidents and Accident Rates from 1998 to 2002	33
Table 2-4. Midblock Traffic Accidents and Accident Rates from 1998 to 2002 (Continued)	34
Table 2-4. Midblock Traffic Accidents and Accident Rates from 1998 to 2002 (Continued)	35
Table 2-5. Intersection Traffic Accidents and Accident Rates from 1998 to 2002.....	36
Table 2-5. Intersection Traffic Accidents and Accident Rates from 1998 to 2002 (Continued)	37
Table 2-5. Intersection Traffic Accidents and Accident Rates from 1998 to 2002 (Continued)	38
Table 2-6. Intersection Traffic Accidents in 2004 by Rate.....	39
Table 3-1. South Lake Washington Redevelopment Assumptions	44
Table 4-1. Second Screening of Roadway and Pedestrian/Urban Design Improvements	62
Table 4-2. Planning Level Cost Estimates	63
Table 4-3. Comparisons of Transit Travel Time Savings (Transit Travel Time Between South 2 nd Street and South Grady Way)	63
Table 4-4. Comparisons of Impacts on Businesses.....	64
Table 4-5. Comparisons of Pedestrian Circulation	64
Table 5-1. Rainier Avenue Transportation Corridor Study Recommendations	66